































- Montageanleitung
- Assembly instructions
- Notice de montage
- Montagehandleiding
- Návod na montáž
- Instrucțiune de montaj
- Navodila za namestitev
- Installationstruktioener




























<p>1</p>  <p>X2</p>	<p>2</p>  <p>X2</p>	<p>3</p>  <p>X2</p>	<p>4</p>  <p>X2</p>
<p>5</p>  <p>X4</p>	<p>6</p>  <p>X4</p>	<p>7</p>  <p>X4</p>	<p>8</p>  <p>X4</p>
<p>9</p>  <p>X6</p>	<p>10</p>  <p>X2</p>	<p>11</p>  <p>X2</p>	<p>12</p>  <p>X2</p>
<p>13</p>  <p>X2</p>	<p>14</p>  <p>X2</p>	<p>15</p>  <p>3,9 x 30mm</p> <p>X8</p>	<p>16</p>  <p>3,9 x 10 mm</p> <p>X14</p>
<p>17</p>  <p>3,9 x 30 mm</p> <p>X6</p>	<p>18</p>  <p>X10</p>		











Pos. 13 Pos. 5






Pos. 1

















Pos. 5 Pos. 13



Pos. 1












Notizen, notes, notities



Notizen, notes, notities





1914-0

Kontrollbeleg
Control Receipt

Prüfnummer/ Inspection number



Service
Am Lindhövel 1
59846 Sundern
Deutschland / Germany / Allemagne / Duitsland



Allgemeine technische Probleme:
Telefon 02935 / 96 53 444



E-Mail:
onlineservice@schulte.de