









- Montageanleitung
- Assembly instructions
- Notice de montage
- Montagehandleiding
- Návod na montáž
- Instrucțiune de montaj
- Navodila za namestitev
- Installationstruktioener








<p>1</p> <p>X2</p>	<p>2</p> <p>X2</p>	<p>3</p> <p>X2</p>	<p>4</p> <p>X2</p>
<p>5</p> <p>X4</p>	<p>6</p> <p>X2</p>	<p>7</p> <p>X2</p>	<p>8</p> <p>X6</p>
<p>9</p> <p>X4</p>	<p>10</p> <p>X2</p>	<p>11</p> <p>X1</p>	<p>12</p> <p>X2</p>
<p>13</p> <p>X6</p>	<p>14</p> <p>ST3.9X30 X6</p>	<p>15</p> <p>X4</p>	<p>16</p> <p>ST3.9X10 X10</p>
<p>17</p> <p>ST3.9X30 X8</p>			



Pos. 3



X2

Pos. 13



X6


Pos. 14








3,9 x 30 mm

X6

Pos. 3




10mm




Pos. 3

Pos. 14


Pos. 3




10mm











Pos. 3





Ø 6 mm




Pos. 13












Pos. 3 Pos. 4










Pos. 1












Pos. 8




Pos. 12









Notizen, notes, notities



Notizen, notes, notities





1915-0

Kontrollbeleg
Control Receipt

Prüfnummer/ Inspection number



Service
Am Lindhövel 1
59846 Sundern
Deutschland / Germany / Allemagne / Duitsland



Allgemeine technische Probleme:
Telefon 02935 / 96 53 444



E-Mail:
onlineservice@schulte.de